

	Type	L #	Hits	Search Text	DBS	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	42	361/601 and vehicle	USPA	2003/07/2 T 4 09:06			0
2	BRS	L2	93	361/601 and mold\$4	USPA	2003/07/2 T 4 08:50			0
3	BRS	L3	74	12 not 11	USPA	2003/07/2 T 4 08:39			0
4	BRS	L4	3	361/601 and fet	USPA	2003/07/2 T 4 08:42			0
5	BRS	L5	48	361/601 and fuse	USPA	2003/07/2 T 4 08:42			0
6	BRS	L6	59	361/601 and fuse	USPA	2003/07/2 T 4 08:42			0
7	BRS	L7	37	16 not 11	USPA	2003/07/2 T 4 08:42			0
8	BRS	L8	18	17 not 12	USPA	2003/07/2 T 4 08:42			0
9	BRS	L9	53	361/622 and vehicle	USPA	2003/07/2 T 4 08:54			0
10	BRS	L10	31	19 not 11	USPA	2003/07/2 T 4 08:44			0
11	BRS	L11	124	361/622 and mold\$4	USPA	2003/07/2 T 4 08:51			0
12	BRS	L12	92	111 not 12	USPA	2003/07/2 T 4 08:51			0
13	BRS	L13	28	361/626 and vehicle	USPA	2003/07/2 T 4 08:56			0
14	BRS	L14	18	113 not 11	USPA	2003/07/2 T 4 08:54			0
15	BRS	L15	0	361/626 and fet	USPA	2003/07/2 T 4 08:57			0
16	BRS	L16	64	361/629	USPA	2003/07/2 T 4 09:01			0
17	BRS	L17	9	361/676 and vehicle	USPA	2003/07/2 T 4 09:03			0
18	BRS	L18	3	361/676 and fet	USPA	2003/07/2 T 4 09:03			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Error rows
19	BRS	L19	28	361/676 and mold\$4	USPA	2003/07/2 T 4 09:04			0
20	BRS	L20	24	361/642 and vehicle	USPA	2003/07/2 T 4 09:10			0
21	BRS	L21	18	120 not 11	USPA	2003/07/2 T 4 09:06			0
22	BRS	L22	1	361/642 and fet	USPA	2003/07/2 T 4 09:09			0
23	BRS	L23	1	361/642 and 361/676	USPA	2003/07/2 T 4 09:09			0
24	BRS	L24	47	361/641 and vehicle	USPA	2003/07/2 T 4 09:14			0
25	BRS	L25	29	124 not 11	USPA	2003/07/2 T 4 09:10			0
26	BRS	L26	27	125 not 120	USPA	2003/07/2 T 4 09:11			0
27	BRS	L27	20	174/17R and vehicle	USPA	2003/07/2 T 4 09:17			0
28	BRS	L28	144	174/50 and vehicle	USPA	2003/07/2 T 4 09:20			0
29	BRS	L29	24	174/50.5 and vehicle	USPA	2003/07/2 T 4 09:17			0
30	BRS	L30	22	129 not 127	USPA	2003/07/2 T 4 09:18			0
31	BRS	L31	133	128 not 129	USPA	2003/07/2 T 4 09:20			0
32	BRS	L32	131	131 not 11	USPA	2003/07/2 T 4 09:20			0